









anger.	
V Nº Hea	ader Sensor Calibration: Step 1 of 2
	Raise the header all the way up and press Set Maximum.
	Set Maximum
	Lower the header all the way down and press Set Minimum.
	set
	Minimum
	and the second
	NOTE: The maximum and minimum only needs to be set once for a combine.





