Task Controller













Select the white text box to begin a task.

Fre	Task	
	999	
	hhh	
	∎ hhh	Ĵ
. itll .wa wa	hhvb	
Press	T to add a new task.	



• Label the task as you desire and press the green check.



22/24 AM	Task	ocumentation Main Ment	
(A			
	corn 2016		E CAR
	99 9		
	∎ hhh		
WAAS	hhh		
	hhvb	–	

The task will load in the selection menu. Highlight the task and press the green check.



The machine and implement will automatically load to the established task. Press Found to add a Field.

12.27 AM	Category	m Main Mens	JP?
SV115.0	📶 Field		Ż
The L	Farm		
	Customer		
	💭 Worker	<u>Hes</u>	J
	S Device		R
	na Product Group	1200	
		1/1	

Highlight field and press the green check.







• Label the field as you desire and press the green check.





Input the size of the field and press the green check.





Highlight the field and press the green check.





	Category	nentation Main Ment	
/ SV115.0	🚜 Field		By I
	🗂 Farm		
	Customer		AR
	Worker		
	Device	_	
	Product Group	▼	12.5%
		1/1	

Highlight farm and press the green check.







• Label the farm as you desire and press the green check.





Highlight the farm and press the green check.





	Category	an Main Mens		117
/ SV115.0	🛲 Field	1266	By .	\geq
	Farm		12. p	2
	Customer			S
	😡 Worker			IJ
. 1111. WAAS	🔊 Device			
	Product Group			
		1/1		1001

• Highlight customer and press the green check.







• Label the customer as you desire and press the green check.





Highlight the customer and press the green check.









To book the task, press

	Booking Confirmation	tiens, III o	
	corn 2016		HE.
	high moisture #566 65.00 ac		fff
	county line		HH
	Lonnie Doubler		
	Gleaner S Series		Ŋ.
	- 😥 0.00 gal		
	Thresher Engagement Total Time: 0 s	125.0%	
	- <mark>Σ</mark> 0.00 gal		in the second
			3311
		annan dianan distangan yan tik ka s	$\mathbb{R}^{(n)}$
Press 🚺	to confirm the booking.		
			Xal